

20030305090

AD-A286 204



DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188



on is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this including this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

2. REPORT DATE
10/28/80

3. REPORT TYPE AND DATES COVERED

4. TITLE AND SUBTITLE
INDUSTRIAL HYGIENE SPECIAL STUDY NUMBER 55 66 0216 81 N NITROSODIMETHYLAMINE, HYDRAZINE, AND 1, 1-DIMETHYLHYDRAZINE EXPOSURES AT THE HYDRAZINE BLENDING FACILITY, RMA, COMMERCE CITY, COLORADO

5. FUNDING NUMBERS

6. AUTHOR(S)
JABARA, J.; DEZAN, J.

7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)
ARMY ENVIRONMENTAL HYGIENE AGENCY
ABERDEEN PROVING GROUND, MD

DTIC
NOV 15 1994

8. PERFORMING ORGANIZATION
REPORT NUMBER
85247R07

9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)

10. SPONSORING/MONITORING
AGENCY REPORT NUMBER

5518
94-35009
DTIC QUALITY INSPECTED 5

11. SUPPLEMENTARY NOTES

12a. DISTRIBUTION/AVAILABILITY STATEMENT

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION IS UNLIMITED

12b. DISTRIBUTION CODE

13. ABSTRACT (Maximum 200 words)

THE PURPOSE OF THIS SURVEY WAS TO DETERMINE EXPOSURE LEVELS TO N-NITROSODIMETHYLAMINE (NDMA), HYDRAZINE, AND 1, 1-DIMETHYLHYDRAZINE (UDMH) DURING VARIOUS JOB OPERATIONS AND WIND CONDITIONS AT THE ROCKY MOUNTAIN ARSENAL (RMA) HYDRAZINE FACILITY.

94 1110 045

DTIC QUALITY INSPECTED 5

14. SUBJECT TERMS
SPILLS, REGULATIONS, CHEMICALS, HUMAN EXPOSURE, NDMA, UDMH

15. NUMBER OF PAGES

16. PRICE CODE

17. SECURITY CLASSIFICATION
OF REPORT
UNCLASSIFIED

18. SECURITY CLASSIFICATION
OF THIS PAGE

19. SECURITY CLASSIFICATION
OF ABSTRACT

20. LIMITATION OF ABSTRACT

Best Available Copy

85247R07
2nd Copy



**UNITED STATES ARMY
ENVIRONMENTAL HYGIENE
AGENCY**

ABERDEEN PROVING GROUND, MD 21810

**INDUSTRIAL HYGIENE SPECIAL STUDY NO. 55-66-0216-81
N-NITROSODIMETHYLAMINE, HYDRAZINE, AND 1, 1-DIMETHYLHYDRAZINE
EXPOSURES AT THE HYDRAZINE BLENDING FACILITY
ROCKY MOUNTAIN ARSENAL
COMMERCE CITY, CO**

FILE COPY

**Rocky Mountain Arsenal
Information Center
Commerce City, Colorado**

**A
E
H
A**

[Handwritten signature]
Distribution limited to US Government agencies only. No
distribution of privileged information evaluation and
control; October 1990. Other requests for this document
must be referred to Commander, Rocky Mountain Arsenal,
Commerce City, CO 80022.



DEPARTMENT OF THE ARMY
US ARMY ENVIRONMENTAL HYGIENE AGENCY
REGIONAL DIVISION - WEST
FITZSIMONS ARMY MEDICAL CENTER
AURORA, COLORADO 80045

Mr. Desan/1h/943-8881

28 OCT 1980

HSE-MW

SUBJECT: Industrial Hygiene Special Study No. 55-66-0216-81,
N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylhydrazine
Exposures at the Hydrazine Blending Facility, Rocky Mountain
Arsenal, Commerce City, CO, 16-27 June 1980

Commander
USA Materiel Development and
Readiness Command
ATTN: DRCSC
5001 Eisenhower Avenue
Alexandria, VA 22333

1. Due to fluctuating wind conditions and apparent multisources of exposure, N-Nitrosodimethylamine (NDMA) is prevalent throughout the facility. Since there is no Occupational Safety and Health Administration (OSHA) Permissible Exposure Limit (PEL) for NDMA, no safe distance can be established within the Hydrazine Blending Facility where respiratory protection is not required. Therefore, respiratory protection should be required for all entries into the Facility when in operation, up to 24 hours after operation, and for all maintenance work on the systems. Since no air purifying respirator has been tested for NDMA, only air supplied or self-contained breathing air respirators are considered adequate.

2. Recommendations are also made for reducing the number of sources of exposures.

Robert G. Grodt
ROBERT G. GRODT, P.E.
LTC, MSG
Chief, Regional Division-West

CP:
HODA (DASG-PSP)
Cdr, ARRCOM (DRSAR-SG)
Cdr, HSC (HSPA-P)
Cdr, PAMC (PVNTMED Actv) (2 cy)
Cdr, RMA (2 cy)
Supt, AHS (HSA-IPM)
Cdr, USAEHA (HSE-M) (2 cy)

Attention For	
AFIS - CH&I	<input checked="" type="checkbox"/>
OTIC - I&B	<input checked="" type="checkbox"/>
Operational	<input type="checkbox"/>
Joint	<input type="checkbox"/>
by	
Distribution	
Availability	
Dist	Availability of Special
A-1	

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1- Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

CONTENTS

<u>Paragraph</u>	<u>Page</u>
1. AUTHORITY.....	1
2. REFERENCES.....	1
3. ABBREVIATIONS.....	1
4. PURPOSE.....	1
5. BACKGROUND.....	1
6. FINDINGS AND DISCUSSION.....	2
a. The Facility.....	2
b. Sampling Strategy.....	2
c. Method of Collection.....	2
d. Method of Analysis.....	2
e. Standards.....	3
f. Comparative Sampling Tenax® vs Thermosorb/®.....	3
g. Ambient Levels.....	4
h. Specific Operations.....	4
i. Potential Sources of Exposure.....	5
j. Medical Surveillance.....	6
7. CONCLUSION.....	6
8. RECOMMENDATIONS.....	6
9. ASSISTANCE.....	7

APPENDIX

A - Introduction.....	A-1
B - Abbreviations.....	B-1
C - Personnel Contacted.....	C-1
D - Sampling Data.....	D-1
E - Results.....	E-1
F - Comparison Tenax® vs Thermosorb/® Results.....	F-1



DEPARTMENT OF THE ARMY
US ARMY ENVIRONMENTAL HYGIENE AGENCY
REGIONAL DIVISION - WEST
FITZSIMONS ARMY MEDICAL CENTER
AURORA, COLORADO 80045

28 OCT 1980

HSE-MW

INDUSTRIAL HYGIENE SPECIAL STUDY NO. 55-66-0216-81
N-NITROSODIMETHYLAMINE, HYDRAZINE, AND 1, 1-DIMETHYLHYDRAZINE
EXPOSURES AT THE HYDRAZINE BLENDING FACILITY
ROCKY MOUNTAIN ARSENAL
COMMERCE CITY, CO
16-27 JUNE 1980

1. AUTHORITY.

a. AR 40-5, Health and Environment, 25 September 1974.

b. Letter, HSE-ZX, Rocky Mountain Arsenal, 29 April 1980, subject:
Request for Technical Assistance, with indorsements.

2. REFERENCES. See Appendix A for a list of references.

3. ABBREVIATIONS. See Appendix B for a list of abbreviations.

4. PURPOSE. To determine exposure levels to N-Nitrosodimethylamine (NDMA), Hydrazine, and 1, 1-Dimethylhydrazine (UDMH) during various job operations and wind conditions at the Rocky Mountain Arsenal (RMA) Hydrazine Facility.

5. BACKGROUND.

a. UDMH upon exposure to air may be converted to trace amounts of the potentially carcinogenic compound N-Nitrosodimethylamine (NDMA). UDMH may also contain small amounts of NDMA as a contaminant (see references 13 & 14). References 2, 4, and 5 found NDMA at various locations during transfer/ blending operations at the RMA facility. Current law* prohibits any occupational exposure to NDMA. To support previous recommendations made for the use of positive pressure, air supplied or self-contained breathing air (SCBA) respirators during all entries into the facility would be logistically and administratively difficult. RMA, therefore, requested a more detailed study be performed (reference 1) to equate job operations and wind directions to exposure levels in order to determine if a minimum safe distance can be established, and to pinpoint the main sources of exposures.

*See paragraph 6E(2)(b) on page 3.

Use of trademarked names does not imply endorsement
by the US Army, but is intended only to assist in
identification of a specific product.

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

b. References 6 and 7 discuss the potential for artificial formation of Nitrosoamines both in Tenax® sorbent and during analytical procedures when artifacts of the compound are present, thus potentially indicating a false high exposure. Also discussed is the low break through volume for NDMA on Tenax® sorbent, thus potentially indicating a false low exposure. Since previous Air Force and Army studies (references 2,4, & 5) used Tenax® sorbent, the scope of this study was expanded to include comparative sampling using Tenax® and Thermosorb/N® sorbents. Thermosorb/N® is a sorbent which inhibits the artificial formation of Nitrosoamine compounds and has good retention for NDMA.

c. In addition to the undersigned, CPT Steven J. Stone, CPT Kenneth E. Hergenrader, Mr. Michael J. Richen, of this Agency and Mr. George Podalsk, USAEHA contributed in conducting this study. The Army Atmospheric Science Laboratory RMA provided all wind data. Personnel contacted during this study are listed in Appendix C.

6. FINDING AND DISCUSSION.

a. The Hydrazine Facility. The hydrazine facility is a transfer/storage facility for hydrazine and UDMH and a blending/storage facility for Aerozine 50. Hydrazine is loaded or down loaded from railroad tank cars, tank trucks, 55 gallon drums, and storage tanks. Four separate loading stations are involved and a diagram of the facility can be found on page D-2.

b. Sampling Strategy. To determine exposure levels six fixed sampling points within the facility and two control points outside the facility were chosen. To characterize exposures at the various transfer/blending operations, upwind, downwind, and downwind samples were also taken. Sampling points are listed in Appendix D.

Method of Collection. Samples were collected on sorbent materials using Disonic 74000 and MSA model G sampling pumps. The adsorption media for hydrazines was 400 mg of 40/60 mesh silica gel coated with concentrated sulfuric acid. For NDMA, comparative samples were taken using 150 mg of Tenax® sorbent (the type of tube used during the previous Army study, reference 2) and commercially prepared Thermosorb/N® cartridges. Sampling rates and times were adjusted (as far as practical) to obtain optimum sample volumes of 40L for NDMA and 60L for the hydrazines. Pump calibrations were verified daily.

Method of Analysis. Hydrazine samples were analyzed by NIOSH Procedure 151 Chemical Analytical Method 248 (see reference 11). The analytical method for NDMA consisted of desorption of samples with 2 ml of methanol and measurement by gas chromatograph equipped with a dual nitrogen-phosphorus detector. The peak identified as NDMA during the analysis of Tenax® and Thermosorb/N® cartridges had a retention time 6.7 min. on a 100 ft. 1/8 in. ID 10% SE-30 column and was confirmed by Gas Chromatography Mass Spectrometry (GC-MS) analysis using the same column.

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1- Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

e. Standards.

(1) Hydrazines

- (a) ACGIH-TLV 1979ed, Hydrazine 0.1 ppm, UDMH 0.5 ppm
- (b) NIOSH Recommended Standard, Hydrazine 0.03 ppm, UDMH 0.06 ppm
- (c) OSHA Standard 29 CFR 1910.1000, Hydrazine 1 ppm, UDMH 0.5 ppm

(2) NDMA

(a) ACGIH-TLV (reference 16) "Because of extremely high toxicity and presumed carcinogenic potential of N-Nitrosodimethylamine, contact should not be permitted by any route."

(b) OSHA Standard 29 CFR 1910.1016, currently there is no established Permissible Exposure Limit (PEL); however reference 14 indicates there is some feeling that a PEL may be established in the order of 1 ppb. To confirm this, Mr. Tipton, OSHA Standards Division, Washington, DC, point of contact listed in reference 15, was contacted. His office has no information concerning the establishment of a PEL. Dr. David West, NIOSH Criteria Document Section, Rockville, MD, was also contacted. A NIOSH Intelligence Bulletin on N-Nitrosodimethylamines will be published in the near future but will not address the establishment of a PEL. Although this standard applies only to mixtures containing more than 1% NDMA and military specification MIL P 25604 limits NDMA contamination in UDMH to 0.01%, UDMH can spontaneously oxidize into NDMA on exposure to air. Therefore, NDMA exposures from NDMA contamination in UDMH accounts for only a portion of the workers overall exposure to NDMA and the less than 1% exclusion is inappropriate.

f. Comparative Sampling Tenax® vs Thermosorb/N® Sorbents. One hundred and forty one pair of comparative samples were taken. Of these, forty pair of results were found to be, and were reported as, less than 0.17 ppb. Of the remaining 101 pair, 96 Tenax® values were below the corresponding Thermosorb/N® values. Tenax® values ranged from 2-275% (average 34%) of the Thermosorb/N® value. Due to the large fluctuation between sample pairs a laboratory efficiency study was conducted. A 150 mg Tenax® tube was fortified with 100 ng NDMA and connected in series to an identical unfortified tube. Laboratory air was pumped through both tubes at 1 Lpm for 100 minutes. The two tubes were desorbed and analyzed as previously described. The fortified tube (front tube) contained 38 ng and the unfortified tube (backup tube) contained 55 ng. Ninety three percent of the 100 ng was recovered from the combination of both tubes of which only 41% of the recovered amount was retained on the fortified front tube. The same procedure was used with two Thermosorb/N® cartridges. A recovery of 96% was obtained from the analysis of the fortified cartridge (front cartridge). The unfortified cartridge yielded an undetectable concentration. A synthetic sample of NDMA was then generated in the laboratory and a commercial 150 mg Tenax® tube was used to collect 100

2nd Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1- Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 10-17 Jun 80

L of sample. Of the theoretical 200 ng, only 28% was recovered. These results confirm reference 6's finding that Tenax® has a poor retention for NDMA and that, under conditions present at RMA, NDMA breakthrough indicating a false low exposure was far more dominant than artificial formation of the compound. Therefore, values reported in Appendix E are those obtained from collection on Thermosorb/N® cartridges unless otherwise stated. A tabulated list of Tenax® vs Thermosorb/N® values are listed in Appendix F. A comparison of the Air Force collection technique, which uses Tenax® tubes containing 2.5 - 3 grams of sorbent, was not made.

g. Ambient Levels. Ambient air samples were collected on 17 June to determine background levels at the hydrazine facility when not in operation. Hydrazines were not detected. However, NDMA was detected in the mixer area, drum storage area, and tank storage area indicating that leaks must exist in the system. Although hydrazines were not detected in the sub-ppm range (the level at which hydrazine standards are established), does not mean that they are not present in the sub-pph range (the level at which NDMA was detected).

h. Specific Operations.

(1) Drum Filling. On 18 June, 55 gallon drums were filled with hydrazine and UDMH. The operation required two workers; one to position the drums with the forklift, the other to make connections and do the filling. The forklift operator wore an M9 Gas Mask, while the filler wore a SCBA respirator. The forklift was not approved for use in explosive atmospheres. Sample results (page E-3) show hydrazines being detected around the filling operation but show no increase in levels throughout the rest of the facility. NDMA levels, however, were not only high around the operation, but were significantly higher than ambient conditions in the sump area, mixer area, and the drum storage area even during the afternoon hydrazine filling operation. This is believed to be due to the residual UDMH from earlier operations.

(2) Drum Rinsing/Steam Cleaning. Seven drums were also cleaned on 18 June. The operation consisted of one employee (in a SCBA respirator) opening the drums and partially filling them with water. Three other employees (without respiratory protection) then rolled the drums on their sides to insure complete rinsing and drained them onto the concrete slab. The contaminated water was drained through a floor drain to the holding sump. A spot check of the seven drums (using a Drager indicator tube) indicated that none contained a significant hydrazine or UDMH residue prior to the rinsing operation. After rinsing, the drums were rolled to the NW corner of the building and steamed. Workers did not wear respiratory protection during steaming. Sample results (page E-3) show hydrazines pose no direct problem although levels were high enough to require respiratory protection during hot steam and steaming.

(3) Transfer from Railroad Car to/from Storage Tanks. These operations required two employees to make and break connections and one employee to transfer gauges (all three wore SCBA respirators). Hydrazine was

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1- Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

transferred on 19 June and Aerozine 50 on 20 and 23 June (see pages E-4, E-5, & E-6). In general, hydrazines pose no problem but NDMA levels were found to be higher than ambient conditions throughout the facility, with levels being greater during Aerozine 50 transfer as would be expected.

(4) Transfer, Tank Truck to/from Storage Tanks. This operation also requires two workers to make and break connections and one to monitor the flow gauges. UDMH was transferred on 20 and 24 June (see pages E-5 & E-7). NDMA levels were found to be higher than during railroad car transfer operations. This could either be due to pure UDMH being transferred (as compared to Aerozine 50 during the railroad car transfer operation), or due to minor leaks in the truck transfer system.

(5) Changing of the UDMH filter on the morning of the 25 June would partially, but not totally, account for the high NDMA levels found that morning (see page E-8 and filter cleaning operation 24 June, page E-7). Residual contaminated water in the drains, on the concrete slabs, and in the sump, in addition to suspected minor leaks in the system, are believed to account for the rest. This would tend to indicate that NDMA levels higher than ambient are present a day following transfer operations.

(6) On 26 June, UDMH was transferred from a truck to a railroad car. However, due to contamination in the UDMH, the railroad car was vented directly to atmosphere in an attempt to install a shorter siphoning port. This was a non-routine operation. High NDMA levels were found throughout the hydrazine facility even at the 7th street perimeter fence.

i. Potential Sources of Exposures (Other than leaks in the System and making/breaking of connections).

(1) The main source of exposure in the mixer area is believed to be the system vent-scrubber. Contaminated air from the system is passed through a water scrubber before being vented to atmosphere. The scrubber water is discharged through a floor drain to a holding sump. Exposures may occur from poor scrubber efficiency and from the air gap between the scrubber and floor drain.

(2) Even though the sump is now being precharged with calcium hypochlorite to oxidize the hydrazines, and a floating plastic cover has been added to reduce exposed surface area, the sump still appears to be a main source of exposure. The capacity of the pump which circulates the sump water appears to be inadequate to insure rapid complete mixing.

(3) Although the bulk of the contaminated water from drum rinsing is removed through a floor drain, the remaining standing water can be a significant source of exposure when a contaminated drum has been rinsed. X

(4) Tank levels must be checked manually with a dip stick, which releases the hydrazines directly to air. X

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1- Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

(5) All floor drains leading to the sump are a potential source of exposure if not equipped with a water trap or if the water level in the trap is not maintained.

j. Medical Surveillance. Hydrazine Facility workers are included in the RMA Medical Surveillance Program and are receiving proper examinations.

7. CONCLUSION. NDMA levels are prevalent throughout the hydrazine facility. Due to fluctuating wind conditions, apparent multisources of exposure, and lack of an established safe exposure limit to NDMA, no safe distance can be established within the facility where respiratory protection is not required. Since no air purifying respirator has been tested for its efficiency and breakthrough times for NDMA, only air supplied or self contained breathing air respirators are considered adequate (see references 14 & 15).

8. RECOMMENDATIONS.

a. The following recommendations are made for reducing the number of sources of exposures at the hydrazine facility until recommendations contained in the study by Sterns and Rogers, for a total upgrade of the facility can be made:

(1) Thoroughly inspect all pipes, valves, gauges, and fittings repairing any leaks found.

(2) Prechlorinate the scrubber water to improve its efficiency by reducing the concentrations of hydrazines and NDMA at the source. This would eliminate the need for a larger pump for circulating the water in the sump. Prechlorinated water could also be used for rinsing the concrete slab after drum rinsing operations. It will be important to maintain a residual chlorine concentration to ensure complete oxidation.

(3) Insure that all floor drains leading to the sump have water traps and that water levels in the traps are maintained.

(4) Provide a separate closed drain for the scrubber, it could be attached to existing plumbing on the downstream side of the floor drain water trap.

(5) Provide fluid level gauges on the storage tanks to eliminate the need for checking tank levels with dip sticks.


b. In the interim, until the facility can be upgraded, require the use of air supplied or self contained respiratory equipment for all entries into the facility when in operation, for all entries within 24 hours after an operation, and for all personnel performing maintenance on the system (see references 14 & 15).

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1- Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

c. Should non-routine operations be performed where the hydrazines are vented directly to air (for example cleaning storage tanks) restrict entry into the area 100 yards beyond the current perimeter.

d. The Safety Office should make determinations as to whether the fork lift currently being used is adequate for use in an area where flammable and combustible liquids are being transferred, and as to whether the smocks currently being used afford adequate splash/spill protection.

9. TECHNICAL ASSISTANCE. Assistance may be obtained by calling USA Environmental Hygiene Agency, Regional Division-West, AUTOVON, 943-8881 or by writing through channels to Commander, USA Health Services Command, ATTN: HSPA-P, Fort Sam Houston, Texas 78234, in accordance with paragraph 1-5, AR 40-5.



JOHN DEZAN, JR.
Industrial Hygienist
Environmental Health
Engineering Branch

for Kenneth E. Hergensacker CPT, MSC
ILT JAMES JABARA
Environmental Science Officer
Regional Division South

APPROVED:



STEVEN J. STONE, P.E., CIH
CPT, MSC
Chief, Environmental Health
Engineering Branch

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1- Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX A

References

1. LTR: HSE-ZX, Rocky Mountain Arsenal, 29 April 1980, Subject: Request for Technical Assistance, with indorsements.
2. USAEHA, Industrial Hygiene Special Study No. 55-35-0128-80, N-Nitrosodimethylamine Exposure During Aerozine 50 Transfer Operation, Rocky Mountain Arsenal, Commerce City, CO, 8-13 July 1979.
3. USAEHA, Industrial Hygiene Special Study No. 35-0101-77, Evaluation of Atmospheric Concentrations of Hydrazine and Unsymmetrical Dimethylhydrazine in and around the Rocky Mountain Arsenal Hydrazine Facility, Denver, CO, 18-22 October 1976 - 17-21 January 1977.
4. LTR: VNL, USAF School of Aerospace Medicine (AFSC), Brooks Air Force Base, TX, 2 February 1979, Subject: Evaluation of Atmospheric Concentrations of NDMA at Rocky Mountain Arsenal.
5. LTR: SFOT, Headquarters, San Antonio Air Logistics Center (AFLC), Kelly Air Force Base, TX, 13 October 1976, Subject: NDMA Analysis at RMA.
6. Roundbehrer, D. P., et al: Nitrosoamine Air Sampling Sorbents Compared for Qualitative Collection and Artifact Formation, J. Analytical Chemistry, Vol. 52, No. 2, pp 273-276, February 1980.
7. Kroll, I. S., et al: Problem of Artifacts in the Analysis of N-Nitroso Compounds, J. Analytical Chemistry, Vol. 50, No. 6, pp 698-700, May 1978.
8. Title 29, Code of Federal Regulations (CFR), 1979 ed, Part 1910, Occupational Safety and Health Standards.
9. American Conference of Governmental Industrial Hygienist (ACGIH), TLV's®, Threshold Limit Values for Chemical Substances and Physical Agents in the Workroom Environment with Intended Changes for 1979.
10. US Department of Health, Education, and Welfare Publication No (NIOSH) 78-172, Criteria for a Recommended Standard...Occupational Exposure to Hydrazines.
11. US Department of Health Education and Welfare Publication No (NIOSH) 77-157A, Hydrazine Compounds in Air, P & CAM 248.
12. Proceeding of the Conference on Environmental Chemistry of Hydrazine Fuels. CEEDO-TR-78-14, Tyndall AFB, September 1978.
13. Fine, D. H., et al: Determination of Dimethylnitrosoamine in Air, Water and Soil by Thermal Energy Analysis, Environmental Science and Technology, Vol. 11, June 1977.

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1- Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX B

Abbreviations

ACGIH	American Conference of Governmental Industrial Hygienist
L	Liters
MSA	Mine Safety Appliance Company
mg	milligrams
mg/m ³	milligrams per cubic meter
mph	miles per hour
ND	not detected
NDMA	N-Nitrosodimethylamine
ng	nanogram
NIOSH	National Institute for Occupational Safety and Health
NO ₂	Nitrogen Dioxide
OSHA	Occupational Safety and Health Act or Administration
ppb	parts per billion
ppm	parts per million
SCBA	Self Contained Breathing Air Respirator
SLpm	Standard liters per minute
RMA	Rocky Mountain Arsenal
TLV	Threshold Limit Value established by ACGIH
UDMH	Unsymmetrical Dimethylhydrazine or 1, 1-Dimethylhydrazine
USAEHA	US Army Environmental Hygiene Agency, Aberdeen Proving Ground, MD

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine,
and 1, 1- Dimethylhydrazine Exposures at the Hydrazine Blending Facility,
RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX C

Personnel Contacted

COL Williams, Cdr PMA
Dr. Throm, Occupational Health Physician/ RMA Health Clinic
Mr. Ursillo, Chief/Plant Operations
Mr. Crabtree, Plant Engineer
Mr. Kim, Safety Engineer/RMA
Mr. Lynch, Foreman/Hydrazine Facility
Mr. Hartberger, Industrial Hygiene Technician, Fitzsimons

APPENDIX D

Sampling Points

- 1 7th Street Fence. Samplers were located 50' west of north gate, 6' above the ground (see Fig D-1).
- 2 West Perimeter Fence. Samplers were located on the south side of the west railroad track gate 6' above the ground (see Fig D-1).
- 3 Sump Area. Samplers were located at the north-east corner of the sump, 3'6" above the ground (see Fig D-1).
- 4 Mixer Area. Samplers were located 2' 6" east of the center of the mixer, 4'6" above the ground (see Fig D-1).
- 5 Drum Storage Area. Samplers were located 7' east of Building 759, 3'6" above the ground (see Fig D-1).
- 6 Tank Storage Area. Samplers were located between storage tanks HAS 2 and HAS 3, 3'4" above the ground.
- 7 Rocky Mountain Arsenal Fire Station.^{*} Sampler was located on the telephone pole at the south-east corner of the fire station, 6' above the ground.
- 8 Fitzsimons.^{*} Sampler was located outside the second floor window of Building 603 at Fitzsimons Army Medical Center.
- A Samplers were attached to a tripod 5' above the ground and located upwind of the operation (see Fig D2-D13).^{**}
- B Samplers were attached to a tripod 5' above the ground and located downwind of the operation (see Fig D2-D13).^{**}
- C Sampler were attached to a tripod 5' above the ground or work platform and located as close to the operation as practical (see Fig D2-D13).^{**}

^{*}Samples collected at sampling points 7 & 8 represent control samples for MDMA.


^{**}Samplers were located upwind and downwind as determined by the dominant wind condition at the start of the sampling period and samplers remained at these positions through the sampling period. However due to fluctuating wind conditions, sampler locations, although placed upwind and downwind at the start of the sampling period, may or may not represent the dominant upwind or downwind positions for the sampling period. See Figures D2-D13 for sampler locations and average wind conditions during specific sampling periods.

Industrial Hygiene Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylhydrazine measures at the Hydrazine Blending Facility, BMA, Commerce City, CO, 16-27 Jun 80

APPENDIX D

SAMPLING POINTS 1-6
17-26 JUNE 80

FIGURE D-1



APPENDIX D

FIGURE D-2: 18 June 1980, Sampler locations during the filling of drums with UDMH (0944-1148 hours).

- (A) 11' NW of the drum.
- (B) 23' SE of the drum.
- (C) Inside the shelter, W of the scale.





FIGURE D-3: 18 June 1980, Sampler locations during the filling of drums with Hydrazine (1352-1420 hours).

- (A) 11' NW of the drum.
- (B) 23' SE of the drum.
- (C) Inside the shelter, W of the scale.



APPENDIX D

FIGURE D-4: 18 June 1980, Sampler locations during drum rinsing operation (1250-1320 hours).

- (A) 18' S of drums.
- (B) 15' N of drums.
- (C) Next to drums.




FIGURE D-5: 18 June 1980, Sampler locations during the steam cleaning of drums (1320-1335 hours).

- (A) 8' S of drum.
- (B) 15' N of drum.
- (C) Next to drums.




FIGURE D-6: 19 June 1980, Sampler locations during all sampling periods.

- (A) 36' N of the railroad car connection port.
(B) 36' S of the railroad car connection port.
(C) On platform leading to the railroad car connection port.

Figure D-6a




Figure D-6b **Sampling periode** **1212-1306 hours**





Figure D-6c **Sampling period: 1306-1400 hours**



APPENDIX D

FIGURE D-7: 20 June 1980, Sampler locations during UDMH transfer from storage tank to truck.

- (A) 36' S of truck connection port.
(B) 45' N of truck connection port.
(C) On platform leading to truck connection port.

Figure D-7a **Sampling period: 0830-0935 hours**




Figure D-7b **Sampling period: 0935-1040 hours**




FIGURE D-8: 20 June 1980, Sampler location during transfer of Aerozine 50 from storage tank to railroad car (1040-1203 hours).

- (A) 45' E of railroad car connection port.
(B) 45' W of railroad car connection port.
(C) On platform leading to railroad car connection port.

APPENDIX D

FIGURE D-9: 23 June 1980, Sampler locations during transfer of Aerozine 50 from railroad car to storage tank (1013-1108 hours).

- (A) S of railroad car (at yellow line).
- (B) N of railroad car (between tracks).
- (C) On platform leading to the railroad car connection port.




FIGURE D-10: 23 June 1980, Sampler locations during sampling of storage tanks US1 and US2.

- (A) Westside of the sampling port platform on tank US2.
- (B) On platform on the west end of storage tanks US1 and US2.
- (C) Westside of the sampling port platform on tank US1.






FIGURE D-11: 23 June 1980, Sampler locations while connecting truck (1452-1517 hours).



- (A) 40' E of the truck connection port.
(B) 50' W of the truck connection port.
(C) On platform leading to the truck connection port.

FIGURE D-12: 24 June 1980, Sampler locations during all sampling periods.



- (A) 35' E of truck connection port.
(B) 35' W of truck connection port.
(C) On the platform leading to the truck connection port.

Sampling periods: 0936-1036 hours
1036-1136 hours
1136-1248 hours
1248-1400 hours
1400-1520 hours

APPENDIX D

FIGURE 13: 26 June 1980, Sampler locations during all sampling periods.

- (A) 35' S of truck connection port.
- (B) 60' N of truck connection port.
- (C) On platform leading to the truck connection port.

Figure 13a

Sampling periods: 0815-0915 hours
0915-1015 hours





Figure 13b

Sampling period: 1015-1120 hours



Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine,
and 1, 1-Dimethylamine Exposures at the Hydrazine Blending Facility, RMA,
Commerce City, CO, 16-27 Jun 80

APPENDIX E

Tabulated Sampling Results
(To be used in conjunction with sampling locations
found in Appendix D)

SAMPLE FORMAT

7th Street Fence

Start of sampling period	_____		
Average wind	_____	SW	4.5
velocity in mph			
		Hyd	0.12
			Hydrazine concentration in <u>ppm</u>
1,1 Dimethylhydrazine - UDMH	0.43		
concentration in <u>ppm</u>		NDMA	0.35
			N-Nitrosodimethylamine concentration in <u>ppb</u>
End of sampling period	_____		

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylamine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX E

Time	17 June 1980 Hydrazine Facility Operation	7th Street Fence	West Perimeter Fence	Sump Area	Mixer Area	Drum Storage Area	Tank Storage Area	Control RMA
0800		SU 4.5 Hyd ND UHM ND NMA <0.17	SU 4.5 Hyd ND UHM ND NMA <0.17	SU 4.5 Hyd ND UHM ND NMA <0.17	SU 4.5 Hyd ND UHM ND NMA 0.43	SU 4.5 Hyd ND UHM ND NMA <0.17		
0900	Ambient Air Sampling							
1000								
1100								NMA <0.17
1200								
1300		SU 8.0 Hyd ND UHM ND NMA <0.17	SU 8.0 Hyd ND UHM ND NMA <0.17	SU 8.0 Hyd ND UHM ND NMA <0.17	SU 8.0 Hyd ND UHM ND NMA 1.7	SE 8.0 Hyd ND UHM ND NMA 0.40	SE 8.0 Hyd ND UHM ND NMA 0.56	
1400								
1500								

*ND - <0.01 ppm

Robert W. Meier
 CPT, MSC
 Chief, Laboratory Branch

Ind Hyg Special Study No. 55-66-021c-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX E

Time	18 June 1980 Hydrazine Facility Operation	A (upwind)	B (downwind)	C (Source)	7th Street Fence	West Perimeter Fence	Sump Area	Mixer Area	Drum Storage Area	Tank Storage Area	Controls Pits RMA
0800											
0900	Checking System										
1000	Filling Five Drums with UDMH from Storage Tank USI	ME 4.5 Hyd MD UDMH MD NMDA 3.36 Fig D-2	ME 4.5 Hyd MD UDMH MD NMDA 2.95 Fig D-2	ME 4.5 Hyd 0.06 UDMH 0.11 NMDA 12.3 Fig D-2	U 4.0 Hyd MD UDMH MD NMDA <0.17	U 4.0 Hyd MD UDMH MD NMDA <0.17	U 4.0 Hyd MD UDMH MD NMDA 1.15	U 4.0 Hyd MD UDMH MD NMDA 1.32	U 4.0 Hyd MD UDMH MD NMDA 1.00	U 4.0 Hyd MD UDMH MD NMDA 0.66	
1100											
1200											
1300	Rinsing & Steam Cleaning Seven Drums	ME 5.0 Hyd MD UDMH MD NMDA 3.73 Fig D-455	ME 5.0 Hyd MD UDMH MD NMDA 3.72 Fig D-455	ME 5.0 Hyd MD UDMH MD NMDA 3.91 Fig D-455	ME 5.0 Hyd MD UDMH MD NMDA <0.17	ME 5.0 Hyd MD UDMH MD NMDA <0.17	ME 5.0 Hyd MD UDMH MD NMDA 0.33	ME 5.0 Hyd MD UDMH MD NMDA 5.05	ME 5.0 Hyd MD UDMH MD NMDA 1.41	ME 5.0 Hyd MD UDMH MD NMDA 0.75	
1400	Filling Six Drums with Hydrazine from RRC 17094	E 4.0 Hyd MD UDMH MD NMDA 6.41 Fig D-3	E 4.0 Hyd MD UDMH MD NMDA 16.5 Fig D-3	E 4.0 Hyd MD UDMH MD NMDA 22.6 Fig D-3							
1500											

*Sample loss in collection due to breakage

Robert W. Meier
CPT, MSC
Chief, Laboratory Branch

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylamine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX E

Time	17 June 1980 Hydrazine Facility Operation	21st Street Perme	Mid- Perimeter Perme	Swamp Area	Water Area	Drum Storage Area	Leak Storage Area	Controls File	RMA
0800		ND 0.5 Hyd Leak RMA <0.17	ND 4.5 Hyd Leak RMA <0.17	ND 4.5 Hyd Leak RMA <0.17	ND 4.5 Hyd Leak RMA 0.99	ND 4.5 Hyd Leak RMA 0.53	ND 4.5 Hyd Leak RMA <0.17		
0900	Ambient Air Sampling								
1000									
1100									
1200		ND 0.0 Hyd Leak RMA <0.17	ND 0.0 Hyd Leak RMA <0.17	ND 0.0 Hyd Leak RMA <0.17	ND 0.0 Hyd Leak RMA 1.7	ND 0.0 Hyd Leak RMA 0.48	ND 0.0 Hyd Leak RMA 0.56		
1300									
1400									
1500									
1600									
1700									

*ND - <0.01ppm

Robert W. Meier
 CPT, MSC
 Chief, Laboratory Branch

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylhydrazine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX E

Time	18 June 1980 Hydrazine Facility Operation	A (upwind)	B (downwind)	C (Source)	7th Street Fence	West Perimeter Fence	Sump Area	Misc Area	Drum Storage Area	Tank Storage Area	Controls Pits RMA
0800	Checking System										
0900											
1000	Filling Five Drums with UDMH from Storage Tank US1	ME 4.5 Hyd 0.04 UDMH 0.11 RMA 3.34 Fig B-2	ME 4.5 Hyd 0.04 UDMH 0.11 RMA 3.34 Fig B-2	ME 4.5 Hyd 0.04 UDMH 0.11 RMA 3.34 Fig B-2	ME 4.0 Hyd 0.01 UDMH 0.01 RMA 1.13	ME 4.0 Hyd 0.01 UDMH 0.01 RMA 1.13	ME 4.0 Hyd 0.01 UDMH 0.01 RMA 1.13	ME 4.0 Hyd 0.01 UDMH 0.01 RMA 1.13	ME 4.0 Hyd 0.01 UDMH 0.01 RMA 1.13	ME 4.0 Hyd 0.01 UDMH 0.01 RMA 1.13	ME 4.0 Hyd 0.01 UDMH 0.01 RMA 1.13
1100											
1200											
1300	Cleaning & Steam Cleansing Seven Drums	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31 Fig B-2	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31 Fig B-2	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31 Fig B-2	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31
1400	Filling Six Drums with Hydrazine from RMC 11004	ME 4.0 Hyd 0.01 UDMH 0.01 RMA 3.31 Fig B-2	ME 4.0 Hyd 0.01 UDMH 0.01 RMA 3.31 Fig B-2	ME 4.0 Hyd 0.01 UDMH 0.01 RMA 3.31 Fig B-2	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31	ME 5.0 Hyd 0.01 UDMH 0.01 RMA 3.31
1500											

*Sample loss in collection due to breakage

Robert W. Meier
ROBERT W. MEIER
 CPT, MSC
 Chief, Laboratory Branch

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylamine
Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX E

Time	19 June 1980 Hydrazine Facility Operation	A (upwind)	B (downwind)	C (Source)	7th Street Fence	West Perimeter Fence	Shop Area	Waste Area	Drum Storage Area	Tank Storage Area	Building 755	Control Pits RMA
0800	Unblended RMC 017094	H 7.0 Hyd MMA <0.17 Fig B-6a	H 7.0 Hyd MMA <0.17 Fig B-6a	H 7.0 Hyd MMA <0.17 Fig B-6a	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17		
0900	Unblended RMC 017048	H 7.0 Hyd MMA <0.17 Fig B-6a	H 7.0 Hyd MMA <0.17 Fig B-6a	H 7.0 Hyd MMA <0.17 Fig B-6a	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17		
1000	Transferred Hydrazine from RMC 17048 to Storage Tank No. 14102	H 7.0 Hyd MMA <0.17 Fig B-6a	H 7.0 Hyd MMA <0.17 Fig B-6a	H 7.0 Hyd MMA <0.17 Fig B-6a	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17	H 6.5 Hyd MMA <0.17		
1100		H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17		
1200		H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17		
1300		H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17		
1400	Unblended RMC 017048	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17		
1500		H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17 Fig B-6a	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17	H 5.0 Hyd MMA <0.17		

o Sample loss in analysis
oo Sample collected on Trench

Robert W. Meier
CPT, MSC
Chief, Laboratory Branch

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylamine
Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX E

Time	Hydrazine Facility Operation	A (upwind)	B (downwind)	C (Source)	7th Street Fence	West Perimeter Fence	Scrap Area	Mixer Area	Drum Storage Area	Tank Storage Area	Building 759	Controls Pits RMA
0800	Spilled RAC Checked Fence Loaded Truck and Transferred RAC into Truck From US-2	ME 3.0 UDMH 0.01 RMA 6.37 Fig B-7a	ME 3.0 UDMH 0.01 RMA 0.60 Fig B-7a	ME 3.0 UDMH 0.02 RMA 0.40 Fig B-7a	ME 6.5 UDMH 0.01 RMA 0.11	ME 6.5 UDMH 0.01 RMA 0.17	ME 6.5 UDMH 0.01 RMA 1.72	ME 6.5 UDMH 0.01 RMA 2.73	ME 6.5 UDMH 0.01 RMA 1.42	ME 6.5 UDMH 0.01 RMA 1.25	ME 6.5 RMA 0.17a	ME 6.5 RMA 0.17
0900												
1000	Transferred RAC Blanket and Unloaded Truck Transferred Acetone 50 From RAC 3 to RAC #1068	ME 7.5 UDMH 0.01 RMA 0.17 Fig B-8	ME 7.5 UDMH 0.01 RMA 2.01 Fig B-8	ME 7.5 UDMH 0.01 RMA 0.18 Fig B-8	ME 6.5 UDMH 0.01 RMA 0.11	ME 6.5 UDMH 0.01 RMA 0.17	ME 6.5 UDMH 0.01 RMA 1.72	ME 6.5 UDMH 0.01 RMA 2.73	ME 6.5 UDMH 0.01 RMA 1.42	ME 6.5 UDMH 0.01 RMA 1.25	ME 6.5 RMA 0.17a	ME 6.5 RMA 0.17
1100												
1200												
1300												
1400												
1500												


*Sample collected on Tensar®
**Sample loss in analysis
***Sample not analyzed for Hydrazine

Robert W. Meier
for ROBERT W. MEIER
CPT, MSC
Chief, Laboratory Branch

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylamine
Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX E

Time	23 June 1980 Hydrazine Facility Operation	A (upwind)	B (downwind)	C (source)	7th Street Fence	West Perimeter Fence	Ramp Area	Mixer Area	Drum Storage Area	Task Storage Area	Controls Pits RMA
0800											
0900	Delay due to charging of pump										
1000											
1100	Transferred Aerosol 50 from REC 17048 to MAS 1	SE 5.0 Hyd <0.01 UDMH 0.01 MDMA 0.42 Fig D-9	SE 5.0 Hyd UDMH 0.02 MDMA 1.83 Fig D-9	SE 5.0 Hyd <0.01 UDMH 0.02 MDMA 2.26 Fig D-9	SE 5.0 Hyd UDMH <0.01 MDMA <0.17	SE 5.0 Hyd UDMH <0.01 MDMA <0.17	SE 5.0 Hyd UDMH 0.01 MDMA 2.28	SE 5.0 Hyd UDMH 0.01 MDMA 0.63	SE 5.0 Hyd UDMH 0.13 MDMA 1.00	SE 5.0 Hyd UDMH 0.01 MDMA <0.17	SE 5.0 Hyd UDMH 0.01 MDMA <0.17
1200											
1300	Sampled tanks US 1 & US 2 Delay awaiting sample results also changed filter in mixer	SE 7.5 Hyd UDMH 0.02 MDMA 0.17 Fig D-10	SE 7.5 Hyd UDMH 0.02 MDMA 3.12 Fig D-10	SE 7.5 Hyd UDMH 0.02 MDMA 2.87 Fig D-10	SE 6.5 Hyd UDMH 0.01 MDMA <0.17	SE 6.5 Hyd UDMH 0.01 MDMA 0.18	SE 7 Hyd <0.01 UDMH 0.01 MDMA 2.89	SE 6.5 Hyd UDMH 0.01 MDMA 3.55	SE 6.5 Hyd UDMH 0.01 MDMA 1.48	SE 6.5 Hyd UDMH 0.01 MDMA 0.75	SE 6.5 Hyd UDMH 0.01 MDMA 0.17
1400											
1500	Booked truck 92793	SE 7.0 Fig D-11	SE 7.0 Fig D-11	SE 7.0 Fig D-11							


CPT, MSC
Chief, Laboratory Branch

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylamine
Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX E

Time	24 June 1980 Hydrazine Facility Operation	A (upwind)	B (downwind)	C (Source)	7th Street Fence	West Perimeter Fence	Sump Area	Mixer Area	Drum Storage Area	Tank Storage Area	Slide 759	Controls Pits RMA
0800												
0900	Delay awaiting sample results											
1000	Purged truck 2793 with UDMH	ME 5.5 Hyd 0.03 UDMH 0.01 MDMA 0.17 Fig D-12	ME 5.5 Hyd 0.03 UDMH 0.06 MDMA 19.5 Fig D-12	ME 5.5 Hyd 0.01 UDMH 0.01 MDMA 1.81 Fig D-12	ME 5.0 Hyd 0.01 UDMH 0.01 MDMA 1.23	ME 5.0 Hyd 0.01 UDMH 0.01 MDMA 1.23	ME 5.0 Hyd 0.01 UDMH 0.01 MDMA 1.23	ME 5.0 Hyd 0.02 UDMH 0.02 MDMA 1.88	ME 5.0 Hyd 0.01 UDMH 0.01 MDMA 0.34	ME 5.0 Hyd 0.01 UDMH 0.01 MDMA 1.83	ME 9 Hyd 0.01 UDMH 0.01 MDMA 0.70	
1100	Transferred UDMH from NAS 3 through 10 micron filter into truck 2793	ME 4.5 UDMH 0.01 MDMA 0.46 Fig D-12	ME 4.5 UDMH 0.02 MDMA 15.3 Fig D-12	ME 4.5 UDMH 0.01 MDMA 1.81 Fig D-12	ME 5.0 Hyd 0.01 UDMH 0.01 MDMA 1.23	ME 5.0 Hyd 0.01 UDMH 0.01 MDMA 1.23	ME 5.0 Hyd 0.01 UDMH 0.01 MDMA 1.23	ME 5.0 Hyd 0.02 UDMH 0.02 MDMA 1.88	ME 5.0 Hyd 0.01 UDMH 0.01 MDMA 0.34	ME 5.0 Hyd 0.01 UDMH 0.01 MDMA 1.83	ME 9 Hyd 0.01 UDMH 0.01 MDMA 0.70	
1200		ME 6.0 UDMH 0.02 MDMA 1.30 Fig D-12	ME 6.0 UDMH 0.04 MDMA 16.4 Fig D-12	ME 6.0 UDMH 0.02 MDMA 8.01 Fig D-12	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.02 MDMA 2.14	ME 6.5 UDMH 0.02 MDMA 0.50	ME 6.5 UDMH 0.02 MDMA 2.33	ME 11 UDMH 0.02 MDMA 0.17	
1300		ME 6.5 UDMH 0.02 MDMA 0.94 Fig D-12	ME 6.5 UDMH 0.02 MDMA 16.2 Fig D-12	ME 6.5 UDMH 0.02 MDMA 1.30 Fig D-12	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.02 MDMA 2.14	ME 6.5 UDMH 0.02 MDMA 0.50	ME 6.5 UDMH 0.02 MDMA 2.33	ME 11 UDMH 0.02 MDMA 0.17	
1400		ME 10 UDMH 0.01 MDMA 0.39 Fig D-12	ME 10 UDMH 0.03 MDMA 18.9 Fig D-12	ME 10 UDMH 0.01 MDMA 1.34 Fig D-12	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.02 MDMA 2.14	ME 6.5 UDMH 0.02 MDMA 0.50	ME 6.5 UDMH 0.02 MDMA 2.33	ME 11 UDMH 0.02 MDMA 0.17	
1500	Removed and inspected filter	ME 10 UDMH 0.01 MDMA 0.39 Fig D-12	ME 10 UDMH 0.03 MDMA 18.9 Fig D-12	ME 10 UDMH 0.01 MDMA 1.34 Fig D-12	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.01 MDMA 2.35	ME 6.5 UDMH 0.02 MDMA 2.14	ME 6.5 UDMH 0.02 MDMA 0.50	ME 6.5 UDMH 0.02 MDMA 2.33	ME 11 UDMH 0.02 MDMA 0.17	

Sample collected on Tenax

Robert W. Meier
CPT, MSC
Chief, Laboratory Branch

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylamine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80


APPENDIX E



Robert W. Meier
 CPT, MSC
 Chief, Laboratory Branch

Ind Hyg Special Study No. 55-66-0216-81, N-Nitrosodimethylamine, Hydrazine, and 1, 1-Dimethylamine Exposures at the Hydrazine Blending Facility, RMA, Commerce City, CO, 16-27 Jun 80

APPENDIX E



*Sample collected on Tensar®

Robert W. Meier
CPT, MSC
Chief, Laboratory Branch

APPENDIX F
Tabulated List of NDMA Sampling Results
Thermosorb® vs Tenax®
Columns of results correlates to those
found in Appendix E left to right, top to bottom
Values given in ppb

17th		18th		19th		20th		23rd		24th		25th		26th	
Therm	Tenax	Therm	Tenax	Therm	Tenax	Therm	Tenax	Therm	Tenax	Therm	Tenax	Therm	Tenax	Therm	Tenax
<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	0.57	<0.17	<0.17	<0.17	1.13	<0.17	<0.17	<0.17
<0.17	<0.17	<0.17	0.45	<0.17	<0.17	0.17	<0.17	<0.17	<0.17	1.23	0.24	<0.17	<0.17	1.86	0.83
<0.17	<0.17	1.15	<0.17	<0.17	<0.17	1.72	<0.17	2.28	0.26	0.71	*	5.30	*	8.40	1.87
0.99	0.17	1.32	3.64	<0.17	<0.17	2.75	0.37	0.63	1.09	1.88	0.89	11.5	0.34	13.5	0.83
0.43	<0.17	1.00	0.31	0.72	0.30	1.42	<0.17	1.00	0.18	0.34	0.17	1.80	0.17	<0.17	0.17
<0.17	<0.17	0.66	0.21	<0.17	<0.17	1.25	0.17	<0.17	<0.17	1.85	<0.17	0.97	<0.17	1.29	*
<0.17	*	<0.17	*	<0.17	*	*	0.17	<0.17	*	<0.17	*	<0.17	*	13.3	1.27
<0.17	*	<0.17	*	<0.17	*	<0.17	*	<0.17	*	<0.17	*	<0.19	*	0.82	<0.17
<0.17	<0.17	3.36	0.78	<0.17	<0.17	<0.17	*	0.42	<0.17	<0.17	<0.17			<0.17	<0.17
<0.17	<0.17	2.95	0.55	<0.17	<0.17	6.37	1.86	1.83	<0.17	19.5	2.15			*	<0.17
<0.17	<0.17	12.5	1.00	<0.17	<0.17	0.60	<0.17	2.26	0.22	0.81	0.17			<0.17	*
1.70	0.26	0.98	<0.17	<0.17	<0.17	6.68	1.53	<0.17	<0.17	*	0.70			<0.17	*
0.40	<0.17	<0.17	<0.17	<0.17	<0.17	7.60	0.48	0.18	<0.17	0.46	<0.17			<0.17	<0.17
0.56	<0.17	0.33	<0.17	<0.17	<0.17	0.26	<0.17	5.55	<0.17	15.3	1.18			5.41	1.98
		5.05	0.99	<0.17	<0.17	2.37	0.31	1.48	<0.17	1.81	0.92			4.73	0.43
		1.41	<0.17	1.57	0.28	<0.17	<0.17	0.75	<0.19	1.30	<0.17			0.69	<0.17
		0.75	<0.17	<0.17	<0.17	2.01	0.75	<0.17	<0.17	16.4	1.00			24.2	1.36
		3.73	<0.17	<0.17	<0.17	0.18	<0.17	3.12	<0.17	4.01	0.33			8.77	0.84
		3.32	<0.17	<0.17	<0.17			2.67	4.96	<0.17	<0.17			9.24	0.33
		3.97	<0.17	0.26	<0.17			2.89	<0.17	2.35	0.44			<0.17	<0.17
		6.61	0.54	0.72	0.22					1.21	*			2.93	*
		16.5	0.88	0.38	0.62					2.14	0.24			14.5	0.37
		22.6	1.05	1.11	*					0.50	<0.17			2.20	<0.17
				*	<0.17					2.33	<0.17			0.23	<0.17
				0.20	<0.17					*	<0.17			*	0.26
				1.87	0.55					0.94	0.50				
				0.46	<0.17					16.2	0.40				
				<0.17	<0.17					1.30	0.34				
				0.59	0.25					0.39	<0.17				
				<0.17	<0.17					18.9	0.85				
										1.54	0.30				

*Comparative samples not run